[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28884; Directorate Identifier 2007-NM-116-AD]

RIN 2120-AA64

Amendment 39-15343 AD 2008-02-13

Airworthiness Directives; Boeing Model 727 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Boeing Model 727 airplanes. This AD requires repetitive external high frequency eddy current (HFEC) inspections of the crown skin for cracks, at certain stringer attachment holes, and repair i necessary. This AD results from a report of cracks at multiple locations on certain areas of the crown skin. We are issuing this AD to detect and correct fatigue cracks of the crown skin, which could result in rapid decompression of the airplane.

DATES: This AD is effective [insert date 35 days after date of publication in the FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of [insert date 35 days after date of publication in the FEDERAL REGISTER].

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at http://www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket

DATE

ROUTING SYMBOL

ATE

ROUTING SYMBOL

ATE

ROUTING SYMBOL

INITIALS/SIG

ROUTING SYMBOL

INITIALS/SIG

ROUTING SYMBOL

ATE

12/01/2007

ROUTING SYMBOL

ANAL

ROUTING SYMBOL

ROU

NITIALS/SIG

[491	0 - 1	3-P]	

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28884; Directorate Identifier 2007-NM-116-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 727 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Boeing Model 727 airplanes. This AD requires repetitive external high frequency eddy current (HFEC)

inspections of the crown skin for cracks, at certain stringer attachment holes, and repair in necessary. This AD results from a report of cracks at multiple locations on certain areas

of the crown skin. We are issuing this AD to detect and correct fatigue cracks of the

crown skin, which could result in rapid decompression of the airplane.

DATES: This AD is effective [insert date 35 days after date of publication in the FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of certain publication listed in this AD as of [insert date 35 days after date of publication in the FEDERAL REGISTER].

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at http://www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket

CONCURRENCES
ROUTING SYMBOL
- | | | |

11-080

- DOS PA

ROUTING SYMBOL

- AEG

12/5/

OUTING SYMBOL

NITIALS/SIG

DATE

ROUTING SYMBOL

INITIALS/SIG

DATE

ROUTING SYMBOL

INITIALS/SIG

ATE

ROUTING SYMBOL

NITIALS/SIG

ROUTING SYMBOL

INITIALS/SIG